

















## ПРАЙС-ЛИСТ Шарошки по металлу

Наименование	Размер, мм	Цена, руб/шт.	Наименование	Размер, мм	Цена, руб/шт.
 A	Ax08	430	 G	Gx08	510
	Ax10	510		Gx10	620
	Ax12	590		Gx12	670
	Ax14	670		Gx14	780
	Ax16	815		Gx16	910
 B	Bx08	—	 I	Ix08	—
	Bx10	—		Ix10	—
	Bx12	845		Ix12	845
	Bx14	—		Ix14	—
	Bx16	—		Ix16	—
 C	Cx08	450	 J	Jx08	450
	Cx10	480		Jx10	510
	Cx12	650		Jx12	580
	Cx14	780		Jx14	780
	Cx16	940		Jx16	895
 D	Dx08	460	 H	Hx08	500
	Dx10	555		Hx10	585
	Dx12	640		Hx12	680
	Dx14	780		Hx14	790
	Dx16	890		Hx16	890
 E	Ex08	510	 L	Lx08	450
	Ex10	575		Lx10	510
	Ex12	655		Lx12	575
	Ex14	760		Lx14	715
	Ex16	870		Lx16	875
 F	Fx08	480	 M	Mx08	490
	Fx10	575		Mx10	590
	Fx12	670		Mx12	655
	Fx14	780		Mx14	785
	Fx16	910		Mx16	910
 K	Kx08	—	 N	Nx08	—
	Kx10	—		Nx10	—
	Kx12	845		Nx12	845
	Kx14	—		Nx14	—
	Kx16	—		Nx16	—
 O	Ox08	—	 P	Px08	—
	Ox10	—		Px10	—
	Ox12	845		Px12	845
	Ox14	—		Px14	—
	Ox16	—		Px16	—